

BRIDGE NO. 90/25N
HOMER HADLEY FLOATING BRIDGE
INSPECTION SUMMARY TABLE (CABLES)
(Continued)

ITEM	DEFICIENCIES (PHOTOGRAPH NOS.)	LOCATION/REPAIR (-#=WATER DEPTH)
O _N	Previous seizing repair unraveling (adjustment made during the inspection) (Photograph No. 25)	-38'
O _s	Light to moderate corrosion covering 30% of cable within the pontoon port	Pontoon port
	Light to moderate corrosion covering 5%-10% of cable	Pontoon port to -4'
P _N	Light corrosion covering less than 5% of cable	-6' to -10'
	Clevis pin of buoy clamp exhibits 30% loss of section due to wear	-24'
P _s	Heavy corrosion, beginning within the pontoon port, covering 100% of cable	Pontoon port to -3'
	Moderate corrosion covering 25%-50% of cable	-3' to -10'
	Moderate corrosion covering 100% of cable	-10' to -50'
Q _N	Light to moderate corrosion, beginning within the pontoon port, covering 50%-75% of cable (Photograph No. 26)	Pontoon port to -10'
	Light corrosion covering 25%-50% of cable	-10' to -35'
	Moderate to heavy corrosion covering 50%-100% of cable. Heaviest coverage occurs from -35 to -45	-35' to -50'
	Missing boater protection buoy (assisted WSDOT with installation of new buoy during inspection)	Surface
	Previous seizing repair, on north side of buoy clamp, in good condition (Photograph No. 27)	-40
	Light to moderate corrosion covering 10% of cable	-50' to -60'
	Cable penetrates mound of silt at lakebed (Photograph No. 28)	-80'
Q _s	Moderate corrosion covering 20% of cable	-7' to -8'
	One wire out-of-lay ½ to ¾ wire diameters	-8' to -12'
	Moderate corrosion covering 5%-20% of cable	-8' to -86'
R _{NE}	No deficiencies	No deficiencies
R _{NW}	Protective rubber sleeve is open up to 4" along top of cable. Exposed areas of cable exhibit moderate corrosion over 10% of area	Pontoon port to -5'
	Scattered, light corrosion covering 10%-25% of cable	-30' to -50'

L

N

H

M

M

N

L

BRIDGE NO. 90/25N
HOMER HADLEY FLOATING BRIDGE
INSPECTION SUMMARY TABLE (CABLES)
(Continued)

ITEM	DEFICIENCIES (PHOTOGRAPH NOS.)	LOCATION/REPAIR (-#=WATER DEPTH)
RSE	Protective rubber sleeve is open up to 4" along top of cable. Exposed areas of cable exhibit moderate corrosion over 10% of area Light corrosion covering 10% of cable	Pontoon port to -5' -5' to -50'
Rsw	Protective rubber sleeve is open up to 4" along top of cable. Exposed areas of cable exhibit moderate corrosion over 10% of area Light corrosion covering 10% of cable	Pontoon port to -5' -5' to -50'

GENERAL NOTES:

- 1) At the locations of all prior seizing repairs (except as noted in table), the repairs were generally found to be adequately secure with no signs of imminent failure.
- 2) The repairs included cleaning the cable above and below the break, after which the broken wires were placed back into the grooves (if possible), followed by placement of seizing cable ties to prevent the wires from further unraveling.

TERMINOLOGY:

The amount of corrosion noted corresponds to the following criteria:

LIGHT -	Light surface corrosion and rusting of the outer layers of wires, no appreciable rust nodules or section loss detected.
LIGHT TO MODERATE -	More significant corrosion with scattered rust nodules 1/16 inch thick, very early stages of section loss due to occasional pitting less than 1/32 inch deep.
MODERATE -	Rust nodules more uniform and typically 1/16 to 1/4 inch thick with more frequent section loss due to pitting, typically still less than 1/32 inch deep, but with occasional pitting up to 1/32 inch deep.
MODERATE TO HEAVY -	Uniform rust nodules typically 1/4 inch thick with uniform section loss due to pitting typically 1/32 inch deep.
HEAVY -	Uniform rust nodules typically 1/4 inch to 3/8 inch thick with uniform section loss due to pitting typically 1/32 to 1/16 inch deep.

BRIDGE NO. 90/25N
HOMER HADLEY FLOATING BRIDGE
INSPECTION SUMMARY TABLE (CABLES)
(Continued)

RECOMMENDED REPAIR AND MAINTENANCE ITEMS

ITEM	PRIORITY
Program replacement of Cables A _{SW} , B _N , C _N , D _N , D _s , E _N , E _s , F _N , F _s , G _s , H _N , L _{4s} , M _N , O _N , and Q _N , due to previous or new broken wires.	2
Replace buoy clamp clevis pin of Cable C _N	2
Perform cathodic protection measurements at all cables near the pontoon ports to verify system functionality and efficiency	2
Monitor the moderate to heavy corrosion near the pontoon port at Cables A _{NW} , B _s , C _s , K _s , L _{1s} , L _{3s} , L _{6N} , L _{6s} , L _s , M _s , N _s , and P _s	4
Monitor Cable L _{1s} at the locations of abandoned cable contact	4

- Emergency Repair:

Repair work requiring immediate action when structures are partially or completely closed.
- Urgent Repair:

Repair work requiring prompt action and must be completed when structural details and bridge crews become available.
- Priority 1:

Damage to primary structural, mechanical or electrical elements which directly affect: Public Safety, Reliability of Transportation System, Protecting Public Investments and Maintaining Legal Federal Mandates.
- Priority 2:


Work should be accomplished within regular work schedule or programmed in the biennial work schedule.
- Priority 3:

Generally a minor nonstructural or 'housekeeping' type of repair, which may evolve into a higher priority if not corrected.
- Priority 4:

A condition that requires the structure to be monitored primarily by the bridge inspection teams, and may evolve into a higher priority




PHOTOGRAPH NO. 1: Pontoon I along bottom joint with Pontoon G. View of concrete overlapping the joint.



PHOTOGRAPH NO. 2: Pontoon L along the north vertical joint at Pontoon M. View of random, small areas of section loss due to forming.




PHOTOGRAPH NO. 3: Cable Asw. View of open protective sleeve and broken cable wires within pontoon port.




PHOTOGRAPH NO. 4: Cable Bn. View of previous seizing repair located approximately 15 feet south of buoy clamp.




PHOTOGRAPH NO. 5: Cable C_N. Typical view of the buoy clamp clevis pin with 50% loss of section due to wear.




PHOTOGRAPH NO. 6: Cable D_N. Typical view of moderate to heavy corrosion with section loss of cable wires from the pontoon port to -2 feet.



PHOTOGRAPH NO. 7: Cable D_N. Typical view of the buoy clamp and buoy clamp clevis pin with 30% to 35% loss of section due to wear.



PHOTOGRAPH NO. 8: Cable E_N. Typical view of light to moderate corrosion from -3 feet to -10 feet.




PHOTOGRAPH NO. 9: Cable F_N. Typical view of the buoy clamp clevis pin with 20% to 25% section loss due to wear.



PHOTOGRAPH NO. 10: Cable H_N. Typical view of the buoy clamp clevis pin with 10% to 15% section loss due to wear.




PHOTOGRAPH NO. 11: Cable H_N at -48 feet. View of one broken wire with light to moderate corrosion.




PHOTOGRAPH NO. 12: Cable H_N at -48 feet. View of seizing repair applied to one broken wire shown in Photograph No. 11.



PHOTOGRAPH NO. 13: Cable JN. Typical view of moderate corrosion from the pontoon port to -3 feet.



PHOTOGRAPH NO. 14: Cable JN at -5 feet. Typical view of aquatic growth and light corrosion.



PHOTOGRAPH NO. 15: Cable J_N at -40 feet. View of the missing buoy clamp clevis pin. Pin was replaced during inspection.




PHOTOGRAPH NO. 16: Cable J_N at -40 feet. View of the newly installed buoy clamp clevis pin shown missing in Photograph No. 15.



PHOTOGRAPH NO. 17: Cable Lls at -160 feet. View of active anchor cable resting on abandoned anchor cable of sunken pontoon.




PHOTOGRAPH NO. 18: Cable Lls at -162 feet. View of anchor cable of sunken, abandoned pontoon resting on top of active anchor cable.




PHOTOGRAPH NO. 19: Cable L3s. Typical view of heavy corrosion at Pontoon Port.


L45².




PHOTOGRAPH NO. 20: Cable M_N at -8 feet. View of failed seizing repair.



PHOTOGRAPH NO. 21: Cable M_N at -8 feet. View of new seizing repair applied to failed seizing repair shown in Photograph No. 20.




PHOTOGRAPH NO. 22: Cable N_N at -20 feet. Typical view of wires out-of-lay up to $\frac{3}{4}$ wire diameters.



PHOTOGRAPH NO. 23: Cable Nn at -25 feet. View of the newly installed buoy clamp clevis pin. Original pin had failed.




PHOTOGRAPH NO. 24: Cable On at -22 feet. Typical view of the buoy clamp clevis pin with 30% to 40% section loss due to wear.



PHOTOGRAPH NO. 25: Cable ON at -38 feet. View of two seizing repairs, one secure and one unraveling (top of photograph). Unraveled repair was adjusted during inspection.



PHOTOGRAPH NO. 26: Cable QN from pontoon port to -10 feet. Typical view of light to moderate corrosion.




PHOTOGRAPH NO. 27: Cable Q_N at -40 feet. View of previous seizing repair immediately north of buoy clamp.



PHOTOGRAPH NO. 28: Cable Q_N at -80 feet. View of cable penetrating lakebed. Socket, pin, eyebar, and fluke anchor were buried at the time of the inspection. Condition was typical for Cables E_N and M_s.



PHOTOGRAPH NO. 29: Cable C_N at south face of Type "A" Fluke Anchor.
View of exposed top portion of fluke.



PHOTOGRAPH NO. 30: Cable G_N at the west corner of Type "A" Fluke
Anchor. View of west corner of the fluke.



PHOTOGRAPH NO. 31: Cable IN at eyebar connection. View of connection between eyebar sections at -191 feet. Condition is typical for eyebars of Type "C" Box Anchors inspected.




PHOTOGRAPH NO. 32: Cable L5s at pontoon connection. View of west pontoon connection at -145 feet.



U5 0001 12000-1 00-30 04OCT06
 00 15 0105:35:00 14:22:48

PHOTOGRAPH NO. 33: Cable L5s at pontoon connection. View of east pontoon connection at -145 feet.




U5 0001 12000-1 00-30 03OCT06
 00 15 0103:35:00 09:33:38

PHOTOGRAPH NO. 34: Cable M_N at cable socket. View of the cable socket condition at -104 feet. Condition is typical of all exposed cable sockets and pin assemblies of Type "A" Fluke Anchors and Type "C" Box Anchors inspected.




PHOTOGRAPH NO. 35: Cable Mn at eyebar. View of the eyebar condition at -105 feet. Condition is typical of all exposed portions of eyebars of Type "A" Fluke Anchors inspected.




PHOTOGRAPH NO. 36: Cable Os at Socket. View of socket at -59 feet. Condition is typical for all sockets of Type "B" Pile Anchors inspected.



PHOTOGRAPH NO. 37: Cable Os at second pile. View of eyebar and pile at -60 feet. Eyebar and pile conditions are typical for all Type "B" Pile Anchors inspected.



PHOTOGRAPH NO. 38: Cable Os at second pile. View of eyebar connection at -61 feet. Conditions of eyebar connection are typical for all Type "B" Pile Anchors inspected.



PHOTOGRAPH NO. 39: Cable Qs at southeast corner of Type "A" Fluke Anchor. View of the exposed southeast corner of fluke.

APPENDIX D

Inspection Forms

UNDERWATER INSPECTION REPORT - FLOATING BRIDGES

NUMBER

90/25N

AGENCY

WSDOT

NAME

Homer Hadley Floating Bridge

ROUTE

I-90 WB

INTERSECTING

Lake Washington

Daniel G. Stromberg

INSPECTOR'S SIGNATURE

P.E.

33597

DATE

9/27-10/4/06

TITLE

IDENTIFICATION NO

HOURS ON SITE

See Dive Forms

DIVE CONTRACTOR

Colins Engineers, Inc.

DIVER'S SIGNATURE

DIVER'S SIGNATURE

PAGE 1 OF 4

STRUCTURE TYPE

N/A

NO SPANS

N/A

SUBSTRUCTURE TYPE

N/A

NO PIERS IN WATERWAY

N/A

FOUNDATION TYPE

N/A

PONTOONS (1)	9/27/06	Diving Operations: Inspected cables Cs, Ds, Es, Fs, Gs, Hs, and Is from pontoon port to a water depth of 50' (Items 9-11). Overall cables were in generally good condition, although some more significant conditions exist which include: appreciable widespread corrosion with light section loss at times on cables in vicinity of the pontoon ports. With regard to the above-mentioned cable corrosion, it was typically found on cables within pontoon port region to approximately 5' to 10' from face of pontoons. The corrosion was mostly moderate to heavy in extent (less than ¼" section loss due to pitting) with occasional areas of heavy corrosion. The corrosion typically affected up to 100% of the surface area of the cables. In addition to the noted corrosion, the cables also had light to moderate aquatic growth, which was most prevalent in the first 10' to 20' of water depth. Except where specifically noted, cables did not exhibit any significant loose/bulging individual wires. In addition to the above general cable findings, the following specific conditions were also encountered: Cable Gs: One wire out of lay up to one wire diameter between water depths of 40 and 45 feet.
PONTOON WALL (2)		
PONTOON BOTTOM (3)		
GROUTED JOINTS (4)		
OTHER JOINTS (5)		
CABLE PORTS (6)		
MARINE GROWTH (7)		
CATHODIC PROTECTION (8)	9/28/06	Diving Operations: Inspected cables ANE, ANW, ASE, ASW, BN, Bs, CN, Cs, Ks, L1s, L2s, L3s, L4s, L5s, L6s, Ls, Ms, Ns, Os, and Ps from pontoon port to a water depth of either 50' or 75' depending on the location boater protection system (Items 9-11). Cable Nn was also inspected from the pontoon port to the anchor. Overall the cables were in generally good condition, although some more significant conditions exist which include: appreciable widespread corrosion with light section loss at times on cables in and around the pontoon ports. With regard to the above-mentioned cable corrosion, it was typically found on cables within pontoon port region to approximately 5' to 10' from face of pontoons. The corrosion was mostly moderate to heavy in extent
ANCHOR CABLES (9)		
CABLE SOCKETS (10)		
MARINE GROWTH (11)		
ANCHORS (12)		
ANCHOR EYEBAR/YOKE (13)		
RIPRAP (14)		
DEBRIS (15)		
9/28/06 Con't	(less than ¼" section loss due to pitting) with occasional areas of heavy corrosion. The corrosion typically affected up to 100% of the surface area of the cables. In addition to the noted corrosion, the cables also had light to moderate aquatic growth, which was most prevalent in the first 10' to 20' of water depth. Except where specifically noted, cables did not exhibit any significant loose/bulging individual wires. In addition to the above general cable findings, the following specific conditions were also encountered: Cable Asw: Open protective sleeve, within the pontoon port, exposing 6 to 8 broken cable wires. Wires could not be seized due to inaccessibility by divers. The broken wires were located between the port opening and 10 feet into the port. Majority of the banding, holding the protective sleeve around the cable, was broken to a water depth of 15 feet. Cable Cn: Buoy clamp clevis pin exhibits 50% loss of section due to wear. Cable Ks: One loose wire bulging out up to one wire diameter at a water depth of 6 feet. Cable L4s: One loose wire bulging out up to one wire diameter between water depths of 42 and 52 feet. Cable L6s: No protective pads present around cable within the pontoon port. In addition to the above-discussed cables, inspection of Pontoon C was performed, with no notable deficiencies observed.	
9/29/06	Diving Operations: Inspected cables Dn, En, Fn, Gn, Hn, In, Jn, Kn, L1N, L2N, L3N, L4N, L5N, L6N, Ln, Mn, On, Pn, and Qn from pontoon port to a water depth of 50' (Items 9-11). Cables On and Qn were also inspected to the anchor. Overall cables were in generally good condition, although some more significant conditions exist which include: appreciable widespread corrosion with primarily minor sections loss on the cable in and around the pontoon ports. With regard to the above-mentioned cable corrosion, it was typically found on cables within pontoon port region to approximately 5' to 10' from face of pontoons. The corrosion was mostly moderate to heavy in extent (less than ¼" section loss due to pitting)	

UNDERWATER INSPECTION REPORT - FLOATING BRIDGES

NUMBER 90/25N AGENCY WSDOT
NAME Homer Hadley Floating Bridge ROUTE I-90 WB INTERSECTING Lake Washington
DATE 9/27-10/4/06
INSPECTOR'S SIGNATURE Daniel G. Stromberg P.E. 33597 HOURS ON SITE See Dive Forms
TITLE IDENTIFICATION NO

DIVE CONTRACTOR Collins Engineers, Inc.
DIVER'S SIGNATURE DIVER'S SIGNATURE
PAGE 2 OF 4

STRUCTURE TYPE N/A NO SPANS N/A
SUBSTRUCTURE TYPE N/A NO PIERS IN WATERWAY N/A
FOUNDATION TYPE N/A

PONTOONS (1)	9/29/06	with occasional areas of heavy corrosion. The corrosion typically affected up to 100% of the surface area of the cables. In addition to the noted corrosion, the cables also had light to moderate aquatic growth, which was most prevalent in the first 10' to 20' of water depth. Except where specifically noted, cables did not exhibit any significant loose/bulging individual wires. In addition to the above general cable findings, the following specific conditions were also encountered: Cable D _N : One wire out of lay up to one wire diameter between water depths of 40 and 42 feet. Phillystran Buoy Rope exhibited moderate abrasion of the sheathing, exposing the rope underneath. Buoy clamp clevis pin exhibits 30%-35% section loss due to wear. Cable E _N : Buoy clamp clevis pin exhibits 30% section loss due to wear. Cable F _N : Buoy clamp clevis pin exhibits 20%-25% section loss due to wear. Cable H _N : Buoy clamp clevis pin exhibits 25% section loss due to wear. One broken cable wire at a water depth of 48 feet, which was repaired by seizing during the inspection. Cable I _N : Buoy clamp clevis pin exhibits 35% section loss due to wear. Cable J _N : Missing buoy clamp clevis pin, which was replaced with assistance of WSDOT personnel. Cable K _N : Buoy clamp clevis pin exhibits 30%-35% section loss due to wear. Cable L2 _N : Two wires out-of-lay up to one wire diameters at water depths between 6 feet and 11 feet. Cable L _N : Buoy clamp clevis pin exhibits 35% section loss due to wear. Cable M _N : Two failed previous seizing repairs. New seizing repairs performed during inspection. Buoy clamp clevis pin exhibits 10% section loss due to wear. Cable O _N : Buoy clamp clevis pin exhibits 30%-40section loss due to wear. Cable P _N : Buoy clamp clevis pin exhibits 30% section loss due to wear. Cable Q _N : Cable penetrates lakebed at a water depth of 85 feet, and is buried for approximately 8 feet before becoming exposed at socket.
PONTOON WALL (2)	Con't	
PONTOON BOTTOM (3)		
GROUTED JOINTS (4)		
OTHER JOINTS (5)		
CABLE PORTS (6)		
MARINE GROWTH (7)		
CATHODIC PROTECTION (8)		
ANCHOR CABLES (9)		
CABLE SOCKETS (10)		
MARINE GROWTH (11)		
ANCHORS (12)		
ANCHOR EYEBAR/YOKE (13)		
RIPRAP (14)		
DEBRIS (15)		

9/29/06 Con't	Anchor QN: Eyebare is exposed for approximately 10 feet. Light corrosion covering up to 10% of socket, pin, and exposed portion of eyebare. In addition to inspecting the above-discussed cables, inspection were performed on Pontoons F, I, L, O, and R. Pontoons were in overall good condition with no significant structural deficiencies encountered. Aquatic growth was light to moderate on all submerged surfaces. Pontoon I: Area of concrete covering joint membrane material at Pontoon H, approximately 20 feet from the south face. Pontoon L: Scattered areas of section loss along the north vertical joint at Pontoon M. Pontoon R: Spall along the west vertical joint at Pontoon Q. Spall was approximately 8 inches long by 4 inches wide with up to 1" penetration.
10/1/06	Diving Operations: Inspected Cables O _s and Q _s from pontoon to anchor. Overall cables in good condition with various states of corrosion and, in some cases, minor loss of section of the cable wires. With regards to the anchor, all connections were observed to be sound and secure with exposed portions of the socket, pin, and eyebars containing light corrosion covering up to 10% of the exposed surfaces. In addition to the above mentioned general conditions, the following specific deficiencies were noted: Cable O _s : Light to moderate corrosion, with negligible section loss of the wires, from the pontoon port to a water depth of 17 feet. Cable Q _s : Moderate corrosion between, with appreciable section loss of the wire, between water depths of 7 feet and 50 feet. One wire out-of-lay, up to ¾ wire diameters, between water depths of 8 feet and 12 feet. Anchor Q _s : Cable is partially buried with the eyebare fully exposed. Ten feet of eyebare exposure. Exposure of the top surfaces and south face of the anchor. Vertical exposure along the south face is approximately 3 feet at the ends and 8 feet in the center of the fluke. Light corrosion covering up to 10% of exposed socket, pin, and eyebare.

UNDERWATER INSPECTION REPORT - FLOATING BRIDGES

NUMBER	90/25N	AGENCY	WSDOT
NAME	Homer Hadley Floating Bridge	ROUTE	I-90 WB
		INTERSECTING	Lake Washington
	Daniel G. Stromberg	DATE	9/27-10/4/06
INSPECTOR'S SIGNATURE	P.E.	33597	HOURS ON SITE See Dive Forms
	TITLE	IDENTIFICATION NO	
DIVE CONTRACTOR	Collins Engineers, Inc.		
DIVER'S SIGNATURE			

STRUCTURE TYPE	N/A	NO SPANS	N/A
SUBSTRUCTURE TYPE	N/A	NO PIERS IN WATERWAY	N/A
FOUNDATION TYPE	N/A		

PONTOONS (1) PONTOON WALL (2) PONTOON BOTTOM (3) GROUTED JOINTS (4) OTHER JOINTS (5) CABLE PORTS (6) MARINE GROWTH (7) CATHODIC PROTECTION (8) ANCHOR CABLES (9) CABLE SOCKETS (10) MARINE GROWTH (11)	10/2/06	ROV Operations: Inspection of Cables C _N , E _N , G _N , and I _N , from a water depth of 50 feet to the anchor or lakebed. Overall, the cables and anchors were in good condition with general condition consisting minimal corrosion and light aquatic growth. With regards to the anchor, all connections were observed to be sound and secure with exposed portions of the socket, pin, and eyebars containing light corrosion covering up to 75% of the exposed surfaces. In addition to the general conditions listed above, the following specific deficiencies were noted: Cable C _N : Moderate corrosion covering up to 50% of the cable surface between 50 feet and 100 feet water depths. Light to moderate corrosion covering up to 20% of the cable surface between water depth of 100 feet and 140 feet (socket). Anchor C _N : Eyebars are exposed for approximately four feet. Anchor exposure is assumed to exist based on previous report. Additional ROV inspection to be performed on 10/4/06. Anchor E _N : Cable penetrates lakebed at 190 feet water depth. No socket, pin, eyebars, or anchor exposure detected. Anchor G _N : Eyebars are exposed approximately 4 feet. Exposure of the top surfaces and north face of anchor. Vertical exposure is typically 1 to 2 feet along the north face. Anchor I _N : Two piece eyebars with first section of eyebars exposed for approximately 15 feet and second section of eyebars (penetrating riprap) exposed for approximately 3 feet. Lakebed covers north end of gravity anchor.
	10/3/06	ROV Operations: Inspection of Cables C _s , E _s , I _s , K _s , M _s , K _N , L _N , and M _N from a water depth of 50 feet to the anchor or lakebed. Overall, the cables and anchors were in good condition with general condition consisting minimal corrosion and light aquatic growth. With regards to the anchor, all connections were observed to be sound and
	10/3/06	Con't secure with exposed portions of the socket, pin, and eyebars containing light corrosion covering up to 10% of the exposed surfaces. In addition to the general conditions listed above, the following specific deficiencies were noted: Cable C _s : Rope tied to cable at a water depth of 137 feet. Anchor C _s : Eyebars are exposed for approximately 3 feet. No anchor exposure detected. Anchor E _s : Eyebars are exposed for approximately 1 foot. Gravel, 6 to 8 inch diameter, is present on the lakebed at approximate location of anchor. No anchor exposure detected. Anchor I _s : Eyebars are exposed for approximately 6 feet. No anchor exposure detected. Anchor K _s : Eyebars are exposed for approximately 3 feet. Gravel, 2 to 4 inch diameter, is present on the lakebed at approximate location of anchor. No anchor exposure detected. Anchor M _s : Cable penetrates lakebed at water depth of 164 feet. No exposure of socket, pin, eyebars, or anchor detected above lakebed. Anchor K _N : Two piece eyebars with first section of eyebars exposed for approximately 10 feet and second section of eyebars (penetrating riprap) exposed for approximately 3 feet. Anchor L _N : Top surfaces and north face of anchor are exposed. Vertical exposure is 3 feet to 4 feet along the north face. Anchor M _N : Eyebars exposed for approximately 6 feet. No portion of the fluke detected.
	10/4/06	ROV Operations: Inspection of Cables C _N , G _s , L1s, L4s, L5s, and L6s from a water depth of 50 feet to the anchor or lakebed. Overall, the cables and anchors were in good condition with general condition consisting minimal corrosion and light aquatic growth. With regards to the anchor, all connections were observed to be sound and secure with the exposed portions of the socket, pin, eyebars, and/or pontoon connections containing light corrosion covering up to 20% of the exposed surfaces. In addition to the general conditions listed above, the following specific deficiencies were noted: Cable C _N : Moderate corrosion covering up to 50% of the cable surface between 50 feet and 100 feet water depths. Light to moderate corrosion covering up to 20% of the cable surface between water depth of 100 feet and 140 feet (socket).